

Release Notes 11.1.1

D50 and D50e Craft Terminal

The information in this document is subject to change without any notice and describes only the product defined in the introduction of this documentation. This documentation is intended for the use of Nokia's customers only for the purposes of the agreement under which the documentation is submitted, and no part of it may be reproduced or transmitted in any form or means without the written permission of Nokia. The documentation has been prepared to be used by professional and properly trained personnel, and the customer assumes full responsibility when using it. Nokia welcomes customer comments as part of the process of continuous development and improvement of the documentation.

The information or statements given in this documentation concerning the suitability, capacity, or performance of the mentioned hardware or software products cannot be considered binding but shall be defined in the agreement made between Nokia and the customer. However, Nokia has made all reasonable efforts to ensure that the instructions contained in the documentation are adequate and free of material errors and omissions. Nokia will, if necessary, explain issues which may not be covered by the documentation. Nokia's liability for any errors in the documentation is limited to the documentary correction of errors. NOKIA WILL NOT BE RESPONSIBLE IN ANY EVENT FOR ERRORS IN THIS DOCUMENTATION OR FOR ANY DAMAGES, INCIDENTAL OR CONSEQUENTIAL (INCLUDING MONETARY LOSSES), that might arise from the use of this documentation or information in it.

This documentation and the product it describes are considered protected by copyright according to the applicable laws.

NOKIA logo is a registered trademark of Nokia Corporation.

Other product names mentioned in this documentation may be trademarks of their respective companies, and they are mentioned for identification purposes only.

Copyright © Nokia Corporation 2004. All rights reserved.

Table Of Contents

New Features in Release 11.1.1	1
<i>D50/D50e Craft Terminal Software</i>	<i>2</i>
<i>Craft Terminal Software Compatibility Matrix.....</i>	<i>3</i>
Status of Limitations in Release 11.1.1	4
<i>D50/D50e Craft Terminal.....</i>	<i>4</i>
Problem Reports in Release 11.1.1	5



Table Of Contents

What's New in Release 11.1.1

New Features in Release 11.1.1

None

Bug Fixes in Release 11.1.1

Software has been enhanced from the Release 11.1.1 onwards, to improve the situation for the bug related to :

Inconsistent Active Alarm display

The Active Alarms display window sometimes displays alarms where the associated ConnID does not exist.

What's New in Release 11.1.1

D50/D50e Craft Terminal Software

D50/D50e Craft Terminal is an existing stand-alone application that connects to a D50 or D50e system over a serial or Ethernet connection to provide user-friendly graphical diagnostic and maintenance capabilities for the system. Craft Terminal supports the functionality of the D50 and D50e systems through its graphical interface.

No new features are implemented as part of Release R11.1.1

What's New in Release 11.1.1

Craft Terminal Software Compatibility Matrix

			D50/D50e Software Releases					
	Release 11.1.1	Release 11.1	Release 11.0.2	Release 11.0.1	Release 11.0	Release 10.0.1	Release 10.0	Release 9.1.x*
Craft Terminal 11.1.1	×	×	×	×	×	×	×	×

* Nokia software support policy allows for support of the current release and two releases back

Status of Limitations in Release 11.1.1

Status of Limitations in Release 11.1.1

Copies of Release Notes for all previous Craft Terminal software releases are available via Nokia Online Services (NOLS) on Support Website of Nokia:

<https://support.nokia.com/broadband>

D50/D50e Craft Terminal Limitations

- Resetting the local counter to “0” in the Craft Terminal GUI connection window does not reset individual card counters. These counters must be reset separately.
- If you are using a serial port connection (PPP connection) with an IP address of 192.168.0.x and an Ethernet card with the same IP address, a connection cannot be established with the D50/D50e. The Ethernet IP address must be changed on the PC before establishing the serial connection.
- To replace a DMT8 Annex-A line card (DMT8-1or DMT8-2, DMT8a3 and DMT8a4) with another type of DMT8 Annex-A line card, the card should be replaced physically before the “Replace” command is issued from the Craft Terminal.

Problem Reports in Release 11.1.1

Problem Reports in Release 11.1.1

Problem No.:	303336
Description:	Inconsistent Active Alarm display.
Note:	Software has been enhanced from the Release 11.1.1 onwards, to improve the situation.
Status:	Open
